

157/2020

FITNESS CERTIFICATE

(To be filled by the Inspecting Officer / Asst. Engineer)

- 1. Name of the Officer: Asharaj R.
- 2. Name of School: Vimalambika Public School Pampady.
- 3. Location with name of Education Dist. / Sub Dist: Kottayam, Pampady.
- 4. Classification of buildings as specified in column 4 of the application for fitness certified & size:
 - Multi storied RCC Building, 1st floor with veranda
 - G.F. -
 - 9x7.20x6.25, 1x3.05x7.20, 6.25x7.25 with veranda
 - 8x7.25x6.25
 - 1x3.05x7.20 - Staff room
 - 1x6.25x3.85 - Staff room above porch
 - 1x8.25x4.75 (Stair room), 1x9.33x4.33 Toilet block
 - 1x6x3.00mts (Washing area), 1x10.60x7.20 (Lab)
 - 2x6.25x7.20
 - 1x10.60x7.20
 - 1x6.35x7.20
 - 1x4.85x2.85 Stair case
 - 1x4.55x2.85
 - 1x4.85x2.85
 - 1x4.55x2.85
- 5. Period for which the certificate is issued - 2020-21
- 6. Nature of defect if any:
 - a) Foundation and Basement
 - b) Superstructure
 - c) Doors and windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks etc.)

Nil
- 7. Any major defects noticed which will render the building unsafe in any manner: Nil
- 8. Whether maintenance works have been done properly: Yes
- 9. Whether the structure is sound or not for conducting classes: Yes, the structure is sound for conducting classes, under normal weather condition.

Note: 1. The stability of the structure should be examined also with reference to location attitude intensity of wind exposure to flood etc.
 2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.



Certified that the school was inspected by me on 28/6/2020 and found to be fit / unfit to conduct classes for the period of 2020-2021 for the reasons stated above,

MANAGER
VIMALAMBIKA PUBLIC E. Mat
PAMPADY P.O., KOTTAYAM

Place Pampady
Date 28/6/2020



Signature: Asharaj R.
Date: 28/6/2020
Designation: ASSISTANT ENGINEER
L.S.G.D SECTION
PAMPADY GRAMA PANCHAYATH